

VEHICLE INSPECTION REPORT

WJ65YTV

Isuzu D-Max 2.5TD

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Buyer To Apply

Details

Reg. date	03/11/2015	Colour	WHITE	CAP Average	£3,575.00
Year	2015	VIN	MPATFS86JFT005093	CAP Below	£2,525.00
Mileage	125,864 Miles Warranted	Body Style	Pickup Double Cab	Gearbox	MANUAL
Fuel Type	Diesel	MOT Due	Expired	Gears	6
GVW	3050kg	CAP Clean	£4,450.00	Axle Combi	4x4

COLLECTED AS NON-RUNNER, GEARBOX FAULT, BRAKES GRINDING, WARNING LIGHTS ON DASH
TWIN SIDE LOAD DOOR, TOW BAR, E/ MIRRORS, HEATED WINDSCREEN, V5 NEW KEEPER DOCUMENT
REFERENCE NUMBER AVAILABLE FOR TAXATION PURPOSES

Tyres

NSF

NSR

OSF

OSR


Spare

Features


- Bluetooth connection
- Air conditioning
- Front electric windows
- Drivers airbag
- Passenger airbag
- Central locking
- Cloth seat trim

Photos





Condition Check




Damage Photos




1: Bonnet
Chipped
Multiple Chips


2: Bonnet
Rusted
Over 5mm




3: Bumper Front
Scratched
Over 100mm Thru Paint





4: Wing nsf
Scratched
Rusted




5: Door nsf
Scratched
Rusted




6: Sill ns
Rusted
Over 5mm



7: Qtr Panel nsr
Scratched
Rusted





8: Roof
Scratched
Over 25mm Thru Paint




9: Qtr Panel osr
Dented
With Paint Damage

10: Door osf
Scratched
Rusted




11: A Post os
Rusted
Over 5mm





13: Bumper Front
Scratched
Over 100mm Thru Paint

12: Wing osf
Scratched
Rusted



14: Screen Front
Chipped
Over 10mm



15: Dash Warning Lights
Displayed
No Action

16: Centre Console Front
Broken
Replace

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
Brakes	OK		
Parking Brake	OK		
EML light illuminated	Fault		
ABS light illuminated	OK		