

VEHICLE INSPECTION REPORT

GK22PXG

Iveco Daily 72-180

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 23/06/2022

Colour WHITE

Axle Combi 4x2

Year 2022

VIN ZCFC670D30D697995

Rear Suspension Steel

Mileage 110,756 Km Warranted

Body Style Box Van

Rear Doors Roller

Fuel Type Diesel

Cab Type DAY CAB

Tail Lift Cantilever

GVW 7200kg

Gearbox AUTOMATIC

UNABLE TO ACCESS REAR


Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Park assist camera
- Drivers airbag
- Digital radio
- Passenger airbag
- Air conditioning
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Panel Front
Cracked
Replace



3: Wing nsf
Dented
Over 30mm

4: Seat Base Cover osf
Torn
Over 3mm



5: Fascia Panel
Broken
Replace

Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
OK		Poor	
Poor		-	
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		